
MODELS 163.136 /154 /172 as of 1.9.99,
163.113 /128 /157 /174 /175
40 % rear seat

i The Bowden cables for vertical and horizontal adjustment at the 40 % rear seat now can be individually replaced. The new routing assignment must be observed when replacing the Bowden cables. The connection at the release handle and at the rear seat support remain the same.

1 Cable, vertical adjustment
2 Cable, horizontal adjustment
3 Clip
4 Rubber straps



P91.12-2598-11

f	Remove and install cables for rear seat adjustment	Models 163.136 /154 /172 as of 1.9.99, 163.113 /128 /157 /174 /175 40 % rear seat	AR91.12-P-1130GH

Parts ordering notes

Part no.	Designation	Quantity
163 920 04 64 38	Cable, horizontal adjustment	1
163 920 12 80	Cable, vertical adjustment	1
000 995 18 14	Clip	1